



Alaska Department of Environmental Conservation Spill Prevention and Response

 search

DEC State of Alaska

[State of Alaska](#) > [DEC](#) > [SPAR](#) > [CSP](#) > [CS Summaries](#) > [ADOT&PF Peger Road Maintenance Station](#)

SPAR PROGRAMS

[Contaminated Sites](#)
[Industry Preparedness](#)
[Prevention and Emergency Response](#)
[Response Fund Administration](#)

INFORMATION

[Report a Spill](#)
[About Us](#)
[Recent Spill Responses](#)
[Approvals and Permits](#)
[Guidance and Forms](#)

ADOT&PF PEGER ROAD MAINTENANCE STATION



Location

Summary Date: June 2009 [View detailed information from database on this site.](#)
Status: Active**Database Name:** ADOT&PF Peger Road Facility**Location:** Southeast corner of Davis and Peger roads, Fairbanks**Latitude:** 64.825963**Longitude:** -147.769907
DEC Contaminated Sites contact: [James Fish](#), Project Manager – 907-451-2117 (Fairbanks)

*[For more photos, please see the photo gallery.](#)


Click on photos or maps for larger versions.

DESCRIPTION

The site houses ADOT/PF facilities including Main Office, Materials Laboratory, Technical Services, Maintenance & Operations, and State Equipment Fleet Maintenance.

PUBLIC HEALTH AND ENVIRONMENTAL CONCERNS

Chlorinated solvents and petroleum products have contaminated the soil and ground water. The chlorinated solvent ground water plume extends off-site to the northwest.



CURRENT STATUS



The delineation of the off-site ground water plume has been completed. Additional on site investigations and evaluation of remediation options will be completed in the future. The plume is fully characterized and the residential wells are all below cleanup levels, but the state will continue to monitor the groundwater to determine the rate of natural degradation of the contamination. Cleanup is contingent on available state funds.

MORE INFORMATION

- ▶ [Fact Sheet 2004 \(PDF 91K\)](#)
- ▶ [Fact Sheet 2006 \(PDF 32MB\)](#)
- ▶ [US Geological Survey website on natural attenuation of chlorinated solvents at this site](#)

Figure 1 - Estimated Contaminant Plume Boundaries, June 2009 ([PDF 318KB](#))

Figure 2 - ADEC Contaminated Sites in Peger Road Study Area ([PDF 11MB](#))



[Glossary/Acronyms](#) [Site Map](#) [Commissioner](#) [Public Notices](#) [External Links](#)

Department of Environmental
Conservation
Division of Spill Prevention and Response
410 Willoughby Ave., Ste. 302
P.O. Box 111800
Juneau, AK 99811-1800

[State of Alaska](#) [myAlaska](#) [My Government](#) [Resident](#) [Business in Alaska](#) [Visiting Alaska](#) [State Employees](#)

State of Alaska © 2011 [Webmaster](#)

